



Oct. 1 - Oct. 6 on vacation

Property Access Checklist

Property ID: \ \ 2		□ WODE	CTAPTED	
Property Address: 3329 High		. ==	STARTED ON:/_/_ COMPELTED ON:/_/_	
1. sport,	h >			
Owner		Renter:		
Owner: Texanon Strig	9105	ELES Kenter:		
Owner: Texanon Strig Address:	100	Phone: Fax:		
		· · · · · · · · · · · · · · · · · ·		
DL	, , -	Cell/Pager: Additional Information:		
Phone: 303 574—140	7	Additional information:		
Cell/Pager:	· · · · · · · · · · · · · · · · · · ·			
	, , , , , , , , , , , , , , , , , , , 			
Notification Letter	Sent:	1(7/6)	By: 7.5mi+h	
Access Agreement	Signed: <u></u>	122 103		
Restoration Agreement	Signed: <u>ර</u>	127103		
☐ Topsoil Sampling (if applicable)	/_	_/	By:	
☐ Disposal Sampling (if applicable)	/_	_/	Ву:	
Garden Sampling (if applicable)	//		By:	
Utility Clearance	Called: / /		Ву:	
Video/Photos (Before)	On: 8 127193		By: P. Sarabia / J. Lynch	
☐ Video/Photos (During)	On://		By:	
☐ Video/Photos (After)	On:/		By:	
☐ Video/Photos (30-Day)	On:/		By:	
☐ Property Completion Agreement	Signed: / /		Ву:	
☐ Final Report	Issued://		Ву:	
Air Monitoring (as applicable)				
Community Crew On:	1 1	By:		
Results:				
	<u> </u>	Т		
Community Crew On:	<u>//</u>	Ву:		
Results:				
Community Crew On:	//_	By:		
Results:				



Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID: 163		
000 / 1116H 21.		
- CXUNNI C OINIGECES		
Phone: 303-574-1404		
Restoration Items in Question:		
Item:		
Item:		
Item:	* * * * * * * * * * * * * * * * * * *	
Item:		
Item:	Table and the desired and the second	
Item:		
Additional Comments:		
I agree restoration is completed, except as noted		
I do not agree restoration is completed .		
I agree that the sprinkler system is working properly following reinstallation by contractor		
Gerafine Drew 15 Mar 04	Jose Lym	3119101
Owner's Signature Date	Contractor's Signature	Date



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 163	-
Property Address: 3329 High St	
Owner: Texange Striggles	
Phone: 303 574 - 1404	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	All Mise. Stuff in backyard
Item:	•
	All Stuff 91019 Sides of garage
item:	
Item:	
ltem:	
Item:	
item:	
Item:	



Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item:	
	Gricks along feace in back
item:	Bricks along fence in back All weeks in backgard
item:	· · · · · · · · · · · · · · · · · · ·
Item:	



Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

Item:	NA
item:	,
Item:	



Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Condition/Type/Species
Evacuated area of yard	1923	Square feet	SEE Sketch mostly sod a little area of large rock
Number of trees > 2 inch trunk diameter	X	Each	N/A
Number of trees <= 2 inch trunk diameter	(Each	
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	NA	Each	N/A
Number of and size of each garden/ flower bed area. Attach a sketch of relative sizes and locations.	Z BedS	Each Square Feet	SEE SKETCH 40SF

> Project Resources Inc.

Item	Quantity	Unit	Condition/Type/Species
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a replacement certificate to the property owner.	Z Beds 40ft ²	\$	AIGO 3 ROSE TSUSHES
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of where each plant will be placed by the contractor.	NA	Each	~ lA
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	1860	SF	SEE SKETCH
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	403	SF	502
Large ROCK	63	SF	Along sides of garage in back



Additional Comments / Instructions:
NOTE SEESKE+CL
ATTY to leave the rose bushes in backyard along fence line. If not possible, wants a replacement certificate.
* Watch out for wasp rests in back yard.
ATTY to leave the two large Bushes in Front to of house.

pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.				
[] I agree	I do not agree	1 agree	☐ I do not agree	
Owner's Signature	Striggles Date 27-03	Contractor's Signature		





U.S. Environmental Protection Agency Vasquez Boulevard I/70 Superfund Site Replacement Certificate

Property Owner	Texanna Striggles
Property Address	3329 High St.
Property Identification Number	163

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)	40 sf	\$ 2.50	\$100.00
Itemized plants		\$7.00	\$
Itemized shrubs/bushes	3	\$12.00	\$36.00
Total			\$136.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$136.00	has been received by the owner in the form of a
replacement certificate, #12590	, to be utilized at Paulino's Gardens, 6300 N.
Broadway, Denver, CO 80216.	

Property Owner's Signature

Date

Contractor's Signature

Date

Access to Property

Owner grants access to property to do restoration on 3329 High st. Contractor will senous sections of fence in backyard to access 3329 High st. and will replace fence after restoration is complete.	
Owner: Juliette Vega	
Owner grants access to property to do	
restoration on 3329 High st. Contractor will	
remove sections of fence in backyard to	
access 3329 High st. and will replace fence	
after restoration is complete.	
_	
Owner Signature: White Contractors Signature: My	

1 St. 1 St.

Χ

<> Ing New Update Test Cancel Reset Exit Ticket # 0000527493-000 has been queued!

Ticket 0000527493 Date 09/12/2003 Time 02:46PM

Oper **JWL670823342**

Rev 000 NEW GRID

Chan WEB Old Tkt 0000527493 Date 09/12/2003 Time 02:46PM Oper **JWL670823342**

Phone 303-487-0377 Ext

Caller JASON LYNCH

Email JLYNCH@PROJECTRESOURCESING.COM

Company PROJECT RESOURCES

Fax 303-295-0990

Address 10 E 55TH AVE

City **DENVER**

State CO Zip 80216

Phone 3034870377

¥1N 163

Alternate Contact MICHELLE SMITH

Done for corps of Engineers / EPA

Work type SOIL EXCAVATION TO A DEPTH OF 12 INCHES F

Explosives N Boring N

Meet time requested N Place **DENVER**

St co Cnty DENVER Addr From 3329

Street HIGH STREET

Nearest Intersecting Street

Latitude Longitude

Location ENTIRE RESIDENTIAL PROPERTY FROM CURB - SOIL EXCAVATION TO A DEPTH OF 12 INCHES

The locate will be completed between 09/12/03 02:47:03 PM and the end of the day 09/16/2003

Grids (T/R/S) 038068W26NE

Members ATCT01 CMSDC00 CMSND14 LVL311 PCND00 PSND14 QLNCND00 QLNCND14 TCHAM2 WCG01

Members - these will be notified by the center

CMSDC00 COMCAST-CATV

LVL311

WCG01

LEVEL 3 COMMUNICATIONS

WILTEL COMMUNICATIONS LLC

COMCAST-CATV/UQ

LEVEL 3 COMMUNICATIONS

WILTEL COMMUNICATION

TCHAM2	TOUCH AMERICASOUTHERN COLORADO AREA	TOUCH AMERICA (FIBER)
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
PCND00	XCEL ENERGY	XCEL ENERGY
CMSDC00	COMCAST-CATV	COMCAST-CATV/UQ
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
ATCT01	AT&T	AT&T

TIER2 MEMBERS - you must notify these members yourself

DIFOOT	DENVER TRAFFIC ENGINEERING OPERATIONS	DNVR TRAFFIC ENG OPERAT.	/20-865-4001
DNVH20	DENVER WATER DEPARTMENT	DENVER WATER DEPT	303-628-6666
WWMG01	WASTEWATER MANAGEMENT DIVISION	WASTEWATER MGMT DIVISION	303-446-3744
DNVPR1	DENVER PARKS AND RECREATION	DENVER PARKS & REC.	303-698-5523





Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: TEXANNA C STRIGGLE	s /e)	Daytime Phone:	(303) Geralu 574 -1404
	Address: 33	29 HIGH ST	
	Address:		
Addresses of Properties covered by	Address:		
this Agreement:	Address:		
	Address:		

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

163





- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact Jennifer Chergo at 303-312-6601 or Pat Courtney at 303-312-6631.

I grant access to my pr	roperties	☐ I do not grant access to my properties			
Devana C. St	riggles				
Signature	() Date 8-27-03	Signature	Date		
	00,00				
☐ I would like to be pre	esent during any sampling	that is required.			
		-			





Consento para el Acesso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

Otorgante (dueño(a) de propiedad) se da consento y autoriza la Agencia para la Proteccion del Medio Ambiente de Los Estado Unidos (EPA) o su representantes autorizado, en conjunto el Cesionario, a entrar y llevar a cabo algunas actividades ambientales acerca de la propiedad describido que sigue:

Dueño de la Propiedad TEXANNA C STRIGGL	
	Dirección: 3329 HIGH ST
Dirección de	Dirección:
Propiedades Cubieto	Dirección:
por este Acuerdo:	Dirección:
	Dirección:

PROPÓSITO DE ACTIVIDADES AMBIENTALES

El EPA solicita el acesso a collectar muestras de tierra y remover tierra que tiene alta concentraciónes de arsénico y/o plomo que podría ser peligroso a su salud. La tierra estará removido y el(los) area(s) excavado(s) estará reemplazado con materials limpias y restaurado. Este trabaja estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de EPA se contactará el Otorgante pesonalmente a discutir el trabajo estar realizado, el Otorgante tendrá la oportunidad a examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termina, el Otorgante estará pedido a revisar el trabajo, confirmar su terminación y cumplir con su aprobación. Después de terminación, el Otorgante recibirá un documento escrito por el EPA que indica la propiedad había sido remediado.

ACCIONES DE LA RESPONDENCIA AMBIENTAL.

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contractors y subcontractors el derecho a entrar la propiedad, en tiempos razonable y sin noticia anterior, para el unico propósito a realizar trabajo. Este acceso debería persistir en efecto hasta que el trabajo había sido terminado en un estado aceptado. El Ortogante tamiben está de acuerdo con:

Página 1 of 2

163





- Remover obstruciónes que incluye botes, remolque, vehículos, jugetes de niños, montones de madera, casas de perros, etc.
- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guia de Salud y Seguridad proveido por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los areas exterior y interior de edificios.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividades o trabajo hecho, o el equipo usado a llevar de cabo los actividades, o hacer cualquier acciones en respecto de la usa de dicho propiedad que podría arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor contacta Jennifer Chergo at 303-312-6601 or Pat Courtney at 303-312-6631.

Si yo permito acceso a	ı mi propiedad	No permito acceso a mi propiedad.			
Firma	Fecha	Firma	Fecha		
☐ Me gustaría ser pre	esento durante de cualqu	nier colleción de muestras.			

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 3329 - 3331 High Street

INPUTS	Variable	Units	House	Garage
General	Mixing depth in yard	cm	2.54	2.54
	Mixing depth in yard	inches	1	1
	Soil density	g/cm3	2.5	2.5
	RBC in soil	mg/kg	400	400
	Bkg in clean fill	mg/kg	50	50
	•		Small	Small
House-specific	Area of the exposure unit	m2	112.5985	71.34953
•	Area of the exposure unit	ft2	1212	768
	Concentration of lead in paint	mg/cm2	26.6	13
	Area of peeling paint	m2	4.157411	6.255162
	Area of peeling paint	ft2	44.75	67.33
COMPUTATIONS	•			
	Mass of lead from paint	ma	1.1E+06	8.1E+05
	Volume of soil	cm3	2.9E+06	1.8E+06
	Mass of soil	ka	7.2E+03	4.5E+03
	Incremental concentration	mg/kg	154.7	179.5
	Maximum acceptable area of po		9.4	12.2
	Maximum acceptable area of po		101.2	131.3
DECISION			OK	ОК

Lead Based Paint Qualification Calculations

Property ID	Positive XRF Readings	SF of Peeling Paint	Comments
163	1789	1.33	House
163	1790	13	House
163	1791	6.25	House
163	1792	0.67	House
163	1793	4	House
163	1794	6	House
163	1795	1	House
163	1796	2	House
163	1800	0.5	House
163	1801	1.67	House Highest XRF Reading Detected 26.6
163	1802	3.33	House
163	1803	5	House
163	1809	1.67	Garage
163	1810	21	Garage
163	1811	1.33	Garage
163	1813	1.33	Garage Highest XRF Reading Detected 13.0
163	1814	21	Garage
163	1815	21	Garage
	······································	· · · · · · · · · · · · · · · · · · ·	
	· · · · · · · · · · · · · · · · · · ·		
			
			
	······································		
		- 	· · · · · · · · · · · · · · · · · · ·
			

House Total SF of Peeling Paint Garage Total SF of Peeling Paint

44.75 67.33



Daily Quality Control Report **VB/I-70** Lead Based Paint Assessment

Date: 07-17-06

Property Location 3729 3331

Type and Location of Tests Performed a

I ype a	nd Location of	Tests Peri	ormed and	Results					
Property ID	XRF Reading #	Lead l POS.	Result NEG.	Direction	Location of Result	Condition	Square Feet	Substrate	Color
163	1789	3.8		€.	3329 DONAL WINDOW FARALE		21/4/12	wood	white
	1790	15,9		E.	south hersen 3329	Intact Ctacker Chipped Pecling	1'X 13'	wood	White
	1791	14.9		\mathcal{E} .	DORCH SOFFIT 3329	Intact Cracked	5"x 15'	Wood	white
	1792	8.0	-	E.	CENTER HOUSE FRAME	Intact (racked)	4'x2"	wood	white
	1793	3.4		E.	CENTEL DOWN BOOK	Intact Cracked Chipped Peeling	2'X2'	WOON	white
	1794	6.0		E,	Douch wiNDOW FRAME 33	Chipped Peeling	6"X6XQ	(Dessell	white
	1795	13.3		E,	3331 HEADED	Intact Cracked Chipped Peeling	61/2	weed	white
	1796	136		E,	3331 Sofit	intact Cracked Chipper Peeling	6"x 4'	Wood	white
	1799		0.01	N.	3331 NE WINDLE FRAME	Intact Cracked Chipped (eeling)		WOOD	white
	1810	10.3		N.	333/ NE WINSOW Sill.	Infact Cracked Onipped Peting	2"x3'	CONCRETE	green,
	1801	26.6		N.	3331 NORTH CONTRE FRANCE	empped Peeling	41115	WOOD	white
	1802	223		N·	3331 NONTH CONTER FORM	Chippen Pecling	10'X4'	was	white
	1813	8.6		N.	333/ N.W. WINDOW	Intact Cracked Chipped Peeling	411×15	Wood	whire
•	1804		0.18	w·	DOWN SPORT	Intact Cracked Chipped Peeling		sreel	white
	1805	7.8		vo.	3331 window FAMO	Intact Cracked Chipped Peeling		wood	white
	1806		0./2	ω.	3381 Soffir	Intact Cracked Chipped Peeling		woods	white
	/807	11.4		w.	331 Centre Winson Floren			10000	white
	1809	8.9		ω.	3329 BAKYAND FRAN	Chipped Peeling		10001	white

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative



Daily Quality Control Report VB/I-70 Lead Based Paint Assessment

Date: 07-17-06


Property Location 2329/3831 High

Type and Location of Tests Performed and Results

_	1 ype ai	nd Location of	Tests Peri	ormed and	1 Results						
	Property ID	XRF Reading #	Lead POS.	Result NEG.	Direction	Location of R	esult	Condition	Square Feet	Substrate	Color
	163	1809	9.6		N.	GAMAGE DOOR	FRAME 333/	Intact Cracked Chippen Peeling	411451	WOOD	BROWN
		1810	6.5		E.	6 Mengo Doox	3331	Intact Cracked Chipped Peeling	7'x3',	W 000	Brown
		1811	10.5		Fs.	WINDOW FRAME	GARAGO.	Intact Cracked Chipped Peeling	411 × 41	10000	BROWN
	·	1813	/3.0		B.	WINDOW FRAME	- 3329	Intact racked Chippes Peling Intact Pracked	4/144	12000	BROOM
ļ		1814	7.8		E,	GALAGE Some	3329	Chipped Pæling	2/X31	2000	BROWN
		1815	9.0		ے.	GAMAGE DOOR	3329	Intact Cracked Chapter Peting	7'X3'	40000	BARREL
						/		Intact Cracked Chipped Peeling			
								Intact Cracked Chipped Peeling			
Į								Intact Cracked Chipped Peeling			
								Intact Cracked Chipped Peeling			
	-							Intact Cracked Chipped Peeling			
								Intact Cracked Chipped Peeling			
								Intact Cracked Chipped Peeling			
								Intact Cracked Chipped Peeling	-		
ı							-	Intact Cracked			
ŀ								Chipped Peeling Intact Cracked		 	
ŀ								Chipped Peeling Intact Cracked			
ŀ			<u> </u>					Chipped Peeling Intact Cracked	- 		
l		L	<u> </u>	L	<u> </u>			Chipped Peeling		<u></u>	L

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative



LBP Assessment Results

Strata Environmental Resource

Date/Time		Component	Subtrate	Side	Condition	Color	Floor	Room	Result	Depth Inde Pbo	;	Pbc Erro
7/22/2005 11:13		WINDOW FRAME			INTACT	WHITE	FIRST	PORCH	POS	4.8	5.72	1.6
7/22/2005 11:14		WINDOW SILL	CEMENT	EAST	INTACT	GREY	FIRST	OUTSIDE		2	18.57	2.4
7/22/2005 11:15		TRIM	WOOD	EAST	INTACT	WHITE	FIRST	PORCH	POS	10	13.9	
7/22/2005 11:18	163	DOOR	WOOD	EAST	PEELING	YELLOW	FIRST	GARAGE	NEG	1.3	0.44	0.2
	<u> </u>					<u> </u>						
											., .	
												l
	-		· · · · · · · · · · · · · · · · · · ·	ļ		ļ. <u></u>						ļ
	1			ļ	ļ		ļ					<u></u>
	<u> </u>			<u> </u>								
				ļ		<u> </u>						
	ļ		ļ	<u> </u>		<u> </u>		· ·				
	ļ			ļ								
	ļ					<u> </u>						
	1											ļ
				<u> </u>	ļ				ļ			_
	-		ļ	 	 							
				-	-				<u> </u>			ļ
	-		ļ	 		<u> </u>						ļ
		-	ļ	-	-							
 			ļ	-	-		-			1		
Notes Deadings		10002			<u> </u>				-			
Note: Readings a	re in mg	J/Cm²		 							_	
	<u> </u>	ted were assessed	4 - 1 - 1 - 11	4411	1:41 44		1		 			

Property ID # 163 / 3329 High Street



East exposure of property (left porch)

White wood window frame contains peeling lead paint

White wood porch trim / soffit contains cracking lead paint





parage CS. Side wark SOD (Rop) 5 SIR 507 (640) SIDE WALK Fence House 4×49 (196) 3329 1+200 S 50D (210) 12×22 > SIDE WALK 509, 14×13-(182) ,50D 17×13'= (221) STREET

- . a -

Real Property Records

Date last updated: Friday, July 11, 2003

O Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property Link to property sales information for this neighborhood Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Commercial

Parcel: 0226234019000

Name and Address Information

Legal Description

STRIGGLES, TEXANNA C

L 24 & N 5 FT OF L 23 & S 1 FT OF L 25 BLK 10

12151 E 48TH AVE

FORDS ADD

DENVER, CO 80239-4434

RESIDENTIAL DUPLEX

Property Address:

Tax District

3329 HIGH ST -3331

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	20600	1640		
Improvements	175500	13970		
Total	196100	15610	0	15610
Prior Year				
Land	12400	1140		
Improvements	138100	12640		
Total	150500	13780	0	13780

Style: Other

Lot Size: 3,870

Year Built: 1902

Zoning: R2

Building Sqr. Foot: 1,281

Reception No.:

Bedrooms:


Recording Date: //

Baths Full/Half: 0/0

Sale Price:

Basement/Finished: 0/0

Mill Levy: 59.855



TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1051095

_	
SITE NAME:	VASQUEZ BLVD AND 170
DOCUMENT DAT	re: <u>07-22-2005</u>
Due to one of the	DOCUMENT NOT SCANNED following reasons:
☐ PHOTOGRAP	HS
☐ 3-DIMENSION	IAL .
□ OVERSIZED	
☑ AUDIO/VISUA	iL .
☐ PERMANENT	LY BOUND DOCUMENTS
☐ POOR LEGIBI	LITY
□ OTHER	
□ NOT AVAILAE	BLE
	CUMENTS NOT TO BE SCANNED es, Data Validation, Sampling Data, CBI, Chain of Custody)
DOCUMENT DES	CRIPTION:
PROPERTY D	ATA CD AND DVD OF PROPERTY VIDEO